

Table 4: Summary of survey results

Address: _____ Date: _____

Location	Product type	Extent	Accessibility	Condition	Surface treatment	Asbestos type	Sample no.	Sampled/assumed	Material assessment score and action	Priority score Action
Store room 2, BC408 ceiling	AIB	Whole ceiling 120 m ²	Medium	Good	Painted one face only	Amosite	1	Sampled 4 samples	5	12
Store room 2, BC408 fire door	Asbestos board on door carcass (AIB)	21 m ²	Medium	Good	Encapsulated by wood in door	Amosite	2	Sampled 1 sample	5	12
Meeting room 2, BC412, ceiling	Asbestos ceiling tiles (AIB)	5 m ²	Medium	Good	Painted one face only	Amosite	3	Sampled 1 sample	5	13
Canteen, BC410, lino on floor	Cushion floor (paper)	5 m ²	Easy	Good – damage to edge	Covered by vinyl	Chrysotile	4	Sampled 1 sample	4	11

Corridor, BC411, electrical switch box	Woven cloth	Possibly four items	Medium	Medium	Unsealed	Chrysotile	5	Assumed	8	14	remove during next campaign
Plant room 2, BC416, lift motor	Brake shoes	2 items	Difficult	Medium	Unsealed	Chrysotile	6	Assumed	4	10 'H'	Vac dust
Plant room 2, BC416, pipe lagging	Pipe insulation	24 linear metres	Easy	Good	Sealed and labelled	Crocidolite Amosite Chrysotile	7	Sampled 6 samples	8	14	remove during next campaign
Plant room 2, BC416, wall panels	Asbestos panels (AIB)	43 m ²	Easy	Good	1 face sealed and labelled	Chrysotile	8	Sampled 4 samples	5	14	monitor weekly

Material scores above 10 have high potential to release fibres

Table 4: Summary of survey results